

## DIGITAL DOOR ENTRY SYSTEMS MANUFACTURER

Uniphones INSPIRO are modern devices with every detail designed to present the newest trends and meet the demands of all customers.

Minimalistic form and high functionality of our devices enables their wide usage in different kinds of investments.

Uniphones coopersate with digital CDN systems, as well as traditional – analog and cyfral/bartar systems.


All the devices produced by ACO are fully compatible with each other.

## Main features - INS - UP720B:

- 2-core digital installation
- magnetic handset hang-up
- hold-function hanging-up without disconnecting the call
- 3 levels of ringing volume
- available in white
- optionally with RJ45 socket

## Main features - INS - UP720M:

- 2-core digital installation
- magnetic handset hang-up
- hold-function hanging-up without disconnecting the call
- 3 levels of ringing volume
- 2 buttons (door opening and additional - functional)
- control over external devices, e.g. additional gateway, barrier, light (without additional cores)
- available in white
- optionally with RJ45 socket








# DIGITAL DOOR ENTRY SYSTEMS MANUFACTURER



### Uniphone measurements INS-UP720









# Uniphones - connecting manner INS-UP720 B/M

#### **INS-UP720 B**



### INS-UP720 M



#### INS-UP720B

- 1) optionally RJ45 socket
- 2) jumpers for address setting
- 3) handset connection terminals
- L+ line +
- GDN ground
- F2 additional function button
- 4) receiver connection joint
- 5) door opening button
- 6) volume regulation switch

#### INS-UP720M

- 1) optionally RJ45 socket
- 2) jumpers for address setting
- 3) handset connection terminals
- L+ line +
- GDN ground
- F2 additional function button
- 4) receiver connection joint
- 5) additional function button
- 6) door opening button
- 7) volume regulation switch 8) jumper for adjusting F2 button



ATTENTION! Be carefull not to let the dirt from the assembly into the electronic board, especially into the SW1 switch. It may be the cause of dirty contacts and uniphone malfunctioning.